



**Universität  
Zürich** UZH

Department of Business Administration

---

# Services & Operations Management

Prof. Dr. Helmut Dietl



## Module Overview

1. Operations strategy
2. Process analytics
- 3. Quality management: SPC**
4. Platform management
5. Sport management



## Learning Goals

After this lecture you should

- be able to calculate upper and lower control limits
- know whether a process is under control or not
- be able to bring a process under control
- be able to calculate performance limits
- be able to use the SPC method in real time
- know the cost effects of decisions in quality management



## Process Control

- Basic idea: Control the process that creates the quality
- SPC (statistical process control)
- Management and control of the quality dimensions (not just "good" vs. "bad" output)
  - How does the data change over time?
  - If a product / service is defective, how far are the values from the AQL (acceptable quality level)?




## Statistical Process Control (SPC)

- SPC identifies the causes for process variations
  - General causes (lead to random variations)
    - affect the entire output
    - are process-immanent
    - avoidance requires new process design
  - Special causes (lead to systematic variations)
    - affect only part of the output
    - are based on avoidable errors (e.g. human failure)
    - avoidance does not require a new process design
- SPC determines process capability
  - Which quality level can be reliably achieved by the process?




## Control Charts






## Why Histograms are Problematic



Problem: Histograms do not report variations over time



## SPC Analyzes Quality Variations over Time








## The Concept of SPC (1/2)


This process is statistically under control because its parameter values are **constant** over time





## The Concept of SPC (2/2)

This process is statistically **not** under control because its parameter values vary over time





## Control Charts: Tasks

Control Charts determine whether a process is statistically under control

*and*


identify the causes of quality variations

*and*

monitor the production process



## Data Collection for Control Charts



### How to construct samples

- **Goal:**
  - Minimize quality variation within each sample
  - Maximize quality variation across samples
- **Criteria:**
  - Constant environmental conditions within a sample
  - Constant materials within a sample
  - Constant personnel (e.g. one shift) within a sample

**Idea:** *If quality variations have special causes, each sample is affected differently*



## Control Charts: Symbols

$\mu$  = Mean

$\sigma$  = Standard deviation

$\bar{X}$  = Sample mean

$\bar{\bar{X}}$  = Average mean (mean of sample means)

R = Sample range

$\bar{R}$  = Average range (mean of sample ranges)



## Control Charts: $\bar{X}$ – Chart and R – Chart

### $\bar{X}$ – Chart

Shows whether a process is under control with respect to its means

- Control limits if parameters are known:  $\bar{\bar{X}} \pm 3 \frac{\sigma}{\sqrt{n}}$
- Control limits if parameters are unknown:  $\bar{\bar{X}} \pm A_2 \bar{R}$

### R – Chart

Shows whether a process is under control with respect to its variations

- Upper control limit (UCL):  $D_4 \bar{R}$
- Lower control limit (LCL):  $D_3 \bar{R}$



<b>n</b>	<b>A<sub>2</sub></b>	<b>D<sub>3</sub></b>	<b>D<sub>4</sub></b>
2	1.88	0	3.27
3	1.02	0	2.57
4	0.73	0	2.28
5	0.58	0	2.11
6	0.48	0	2.00
7	0.42	0.08	1.92
8	0.37	0.14	1.86
9	0.34	0.18	1.82
10	0.31	0.22	1.78

Quelle: Grant E.L. (1988): Statistical Quality Control, 6. Aufl.



<b>n</b>	<b>A<sub>2</sub></b>	<b>D<sub>3</sub></b>	<b>D<sub>4</sub></b>
11	0.29	0.26	1.74
12	0.27	0.28	1.72
13	0.25	0.31	1.69
14	0.24	0.33	1.67
15	0.22	0.35	1.65
16	0.21	0.36	1.64
17	0.20	0.38	1.62
18	0.19	0.39	1.61
19	0.19	0.40	1.60
20	0.18	0.41	1.59





## Example 1: Diameter

- Diameter, standard deviation = 0.09 nm
- Table shows results of 5 samples (sample size = 4)
- Is process under control?

Sample	Observations				Mean	Range
	1	2	3	4		
1	0.51	0.63	0.39	0.35	0.47	0.28
2	0.50	0.56	0.42	0.64	0.53	0.22
3	0.68	0.49	0.53	0.62	0.58	0.19
4	0.45	0.33	0.47	0.55	0.45	0.22
5	0.70	0.58	0.64	0.68	0.65	0.12




## Example 1: $\bar{X}$ – Chart

### $\bar{X}$ – Chart

- $\bar{\bar{X}} = \frac{0.47+0.53+0.58+0.45+0.65}{5} = 0.536$
- $UCL = 0.536 + 3 * \left(\frac{0.09}{\sqrt{4}}\right) = 0.536 + 0.135 = 0.671$
- $LCL = 0.536 - 0.135 = 0.401$

→ Process is under control with respect to its means






## Example 1: R-Chart

### R – Chart

- $\bar{R} = \frac{0.28+0.22+0.19+0.22+0.12}{5} = 0.206$
- $UCL = 2.28 * 0.206 = 0.47$
- $LCL = 0 * 0.206 = 0$

→ Process is under control with respect to its range





## Example 2: Abrasion

- Tire abrasion in nm, standard deviation unknown
- 20 samples à 10 tires (see Table)
- Is the process under control?

Sample	Average	Range	Sample	Average	Range
1	95.72	1.0	11	95.80	0.6
2	95.24	0.9	12	95.22	0.2
3	95.18	0.8	13	95.56	1.3
4	95.44	0.4	14	95.22	0.5
5	95.46	0.5	15	95.04	0.8
6	95.32	1.1	16	95.72	1.1
7	95.40	0.9	17	94.82	0.6
8	95.44	0.3	18	95.46	0.5
9	95.08	0.2	19	95.60	0.4
10	95.50	0.6	20	95.74	0.6



## Example 2: Control Limits

- $\bar{\bar{X}} = 95.398$
- $\bar{R} = 0.665$
- $UCL (\bar{X} - \text{Chart}) = 95.398 + 0.31 * 0.665 = 95.60$
- $LCL (\bar{X} - \text{Chart}) = 95.398 - 0.31 * 0.665 = 95.19$
- $UCL (R - \text{Chart}) = 1.78 * 0.665 = 1.18$
- $LCL (R - \text{Chart}) = 0.22 * 0.665 = 0.15$




## Example 2: Sample Mean

Sample	Average	Range	Sample	Average	Range
1	95.72	1.0	11	95.80	0.6
2	95.24	0.9	12	95.22	0.2
3	95.18	0.8	13	95.56	1.3
4	95.44	0.4	14	95.22	0.5
5	95.46	0.5	15	95.04	0.8
6	95.32	1.1	16	95.72	1.1
7	95.40	0.9	17	94.82	0.6
8	95.44	0.3	18	95.46	0.5
9	95.08	0.2	19	95.60	0.4
10	95.50	0.6	20	95.74	0.6

→ Process is not under control with respect to its mean



## Example 2: $\bar{X}$ -Chart



→ Process is not under control with respect to its mean



## Example 2: Sample Range


Sample	Average	Range	Sample	Average	Range
1	95.72	1.0	11	95.80	0.6
2	95.24	0.9	12	95.22	0.2
3	95.18	0.8	13	95.56	1.3
4	95.44	0.4	14	95.22	0.5
5	95.46	0.5	15	95.04	0.8
6	95.32	1.1	16	95.72	1.1
7	95.40	0.9	17	94.82	0.6
8	95.44	0.3	18	95.46	0.5
9	95.08	0.2	19	95.60	0.4
10	95.50	0.6	20	95.74	0.6

→ Process is not under control with respect to its range






## Example 2: R-Chart



→ Process is not under control with respect to its range




## Analyzing Control Charts: Process 1



Process 1 is an ideal process




## Analyzing Control Charts: Process 2



Process 2 is under control, but problematic because of an (upward) trend




## Analyzing Control Charts: Process 3



Process 3 is under control, but problematic because of 5 subsequent observations above  $\bar{X}$




## Analyzing Control Charts: Process 4



Process 4 is under control, but problematic because of a sudden shift




## Analyzing Control Charts: Process 5



Process 5 is under control, but problematic because the values are approaching the UCL



## Analyzing Control Charts: Process 6



Process 6 is under control, but problematic because of increasing process variance



## Performance Limits

### Control limits

- are based on actual output data
- help to distinguish special from general (process immanent) causes of quality variations

### Performance limits


- predict future process performance
- are calculated for processes which are under control
- make no sense for processes which are not under control






## Performance Limits versus Specification Limits (1/2)

**Undesirable situation:**




**Extremely undesirable situation:**






## Performance Limits versus Specification Limits (2/2)

**Vulnerable situation:**



**Highly desirable situation:**





## Capability Index (for symmetric processes)

Assumption: Process mean is centered between specification limits

$$C_P = \frac{\text{Permissible range}}{\text{Actual range}}$$

Respectively,

$$C_P = \frac{\text{Upper Specification Limit (USL)} - \text{Lower Specification Limit (LSL)}}{6 * \sigma}$$

Process is capable if  $C_P \geq 1$

Recommended minimum  $C_P = 1.33$

Six Sigma Quality process:  $C_P = 2$



## Special Case: Capability Index for Asymmetric Processes

If process mean is not centered between specification limits:

$$C_{pk} = \min \left[ \frac{USL - \mu}{3\sigma} ; \frac{\mu - LSL}{3\sigma} \right]$$

$C_{pk}$  Capability Index for asymmetric Processes

$USL$  upper specification limit

$LSL$  lower specification limit

$\mu$  mean of the process (center between  $UCL$  and  $LCL$ )

$\sigma$  standard deviation of the process



## Process Capability

### Specification Limits


- Describe desirable tolerance ranges
- Embody the quality demands of the customers

### Process skills

- Can only be determined for processes that are under control. If there are uncontrolled special influences, the process capabilities cannot be reliably forecast
- A process that is under control has the ability to stay within performance limits
- But: Even a process that is under control may produce defective products (i.e. outside the specification limits)




## Ideal Situation: $CP > 1$





## Bad, But Solvable: $CP > 1$





## Not Solvable: $CP \ll 1$

